



This shot was taken seven years ago by a Delta Truss salesman in northwest lower Michigan. Can you guess if the trusses were built into and through the chimney or if the bottom chord was cut to make room for the chimney? Send your guess, along with your name and phone number, to partingshots@sbcmag.info by May 2, 2005. If your correct answer is selected, you will win a copy of the WTCA/TPI publication, Building Component Safety Information BCSI 1-03: Guide to Good Practice for Handling, Installing and Bracing of Metal Plate Connected Wood Trusses. We'll print the photo's story and the winner's name in the June/July 2005 issue of SBC Magazine. SBC



For reader service, go to www.sbcmag.info/hain.htm



www.sbcmag.info

Dear Reader:

Copyright © 2005 by Truss Publications, Inc. All rights reserved. For permission to reprint materials from SBC Magazine, call 608/310-6706 or email editor@sbcmag.info.

The mission of Structural Building Components Magazine (SBC) is to increase the knowledge of and to promote the common interests of those engaged in manufacturing and distributing of structural building components to ensure growth and continuity, and to be the information conduit by staying abreast of leading-edge issues. SBC will take a leadership role on behalf of the component industry in disseminating technical and marketplace information, and will maintain advisory committees consisting of the most knowledgeable professionals in the industry. The opinions expressed in SBC are those of the authors and those quoted solely, and are not necessarily the opinions of any of the affiliated associations (SBCC, WTCA, SCDA & STCA).

